

Final Reclamation Inspection

January 30th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333584

Inspection Document #: 714000376

La Plata County, CO

Township: SENW 15 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
 Location Name: Dunavant 01-15U 1, 3
 Location ID: 333584



1/30/24
 +37.193924,-107.581444
 351° N



1/30/24
 +37.192381,-107.598446
 358° N

DUNAVANT 01-15U 1 SIMCOB LLC ELEVATION: 6865 API #: 06-067-09584 DWR #: 70388-F NAME OF TRIBE: N/A LEASE TYPE: FEE LEASE #: N/A CA #: 00053003 SURFACE LOCATION: SENW SEC 15 - T34N - R7W 2050 FWL 1925 FWL BOTTOM HOLE LOCATION: SAME AS SURFACE LOCATION LATITUDE: -97.19293846 LONGITUDE: -107.5884244 NEAREST ADDRESS: 404 CR 516 CONTROL CENTER 24 HR. PHONE #: 970-242-6918 EMERGENCY CONTACT #: 911	DUNAVANT 01-15U 3 SIMCOB LLC ELEVATION: 6801 API #: 06-067-09580 DWR #: 70668-F NAME OF TRIBE: N/A LEASE TYPE: FEE LEASE #: N/A CA #: 00053002 SURFACE LOCATION: SENW SEC 15 - T34N - R7W 2050 FWL 1927 FWL BOTTOM HOLE LOCATION: SENW SEC 15 - T34N - R7W 875 FWL 892 FWL LATITUDE: -97.19293616 LONGITUDE: -107.5894530 NEAREST ADDRESS: 404 CR 516 CONTROL CENTER 24 HR. PHONE #: 970-242-6918 EMERGENCY CONTACT #: 911
--	---

Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: Dunavant 01-15U 1, 3
Location ID: 333584



1/30/24
+37.192446,-107.598409
109° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. CA for weedy debris observed in the previous inspection has been addressed.

API #: 067-06544, 09580

Inspection Photos
Location Name: Dunavant 01-15U 1, 3
Location ID: 333584

1/30/24
+37.192748,-107.598202
356° N



Photo 3. View of the eastern interim reclamation facing north.

Inspection Photos
Location Name: Dunavant 01-15U 1, 3
Location ID: 333584

1/30/24
+37.193261,-107.598541
330° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of crested wheatgrass and smooth brome.

API #: 067-06544, 09580