

# Final Reclamation Inspection

January 30th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333472

Inspection Document #: 714000377

La Plata County, CO

Township: NWSE 16 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Couch 01-16U 2, 3, 4  
Location ID: 333472

1/30/24  
+37.190484,-107.610202  
226° SW



**Photo 1.** View of the disturbance from the entrance facing center.





Inspection Photos  
Location Name: Couch 01-16U 2, 3, 4  
Location ID: 333472

1/30/24  
+37.187960,-107.604358  
228° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Southern interim reclamation area facing southwest.

API #: 067-09326, 09325,  
09324





**Photo 3.** View of erosion forming along installed stormwater BMPs.  
Current stormwater round river rock BMPs remain inadequate for this  
area.



Inspection Photos  
Location Name: Couch 01-16U 2, 3, 4  
Location ID: 333472



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Additional gully erosion observed forming in the southern interim reclamation area.

API #: 067-09326, 09325,  
09324



Inspection Photos

Location Name: Couch 01-16U 2, 3, 4

Location ID: 333472



Photo 5. View of weedy debris observed around well head # 2.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-09326, 09325,  
09324



Inspection Photos

Location Name: Couch 01-16U 2, 3, 4

Location ID: 333472



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** View of unused oil and gas pipe equipment on location.

API #: 067-09326, 09325,  
09324



Inspection Photos  
Location Name: Couch 01-16U 2, 3, 4  
Location ID: 333472

1/30/24  
+37.190064,-107.611595  
248° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 7.** View of reference area comprised of tumble mustard and kochia.

API #: 067-09326, 09325,  
09324