

Final Reclamation Inspection

January 30th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326328

Inspection Document #: 714000379

La Plata County, CO

Township: NWNW 17 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Robert McCoy A 1
Location ID: 326328

1/30/24
+37.195215,-107.637503
22° N



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos
Location Name: Robert McCoy A 1
Location ID: 326328

1/30/24
+37.195148,-107.637724
355° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of western interim reclamation area facing west.
Interim vegetation was not fully assessed due to snowy conditions.

API #: 067-07845

Inspection Photos
Location Name: Robert McCoy A 1
Location ID: 326328



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Weedy kochia debris observed around active equipment.

API #: 067-07845