

Final Reclamation Inspection

January 31, 2024

Operator: CHESAPEAKE OPERATING LLC- 16660

Location ID: 426383

Inspection Document #: 697505104

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: BRENT 20-8-66 1H

Location ID: 426383



Photo 1. Photo taken from the well location, facing North. Well location meets Rule 1004 standards and is reflective of reference areas.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos

Location Name: BRENT 20-8-66 1H

Location ID: 426383



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: BRENT 20-8-66 1H
Location ID: 426383



Photo 5. Photo taken from the stockpile on location, facing South. Photo illustrates the stockpile has established with perennial vegetation.