

Inspection Photos

Loc: 333447

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 2/5/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the wellsite.



Inspection Photos



Photo 2. Facing toward the wellhead. There is a dripping leak that needs to be repaired.

