

# Inspection Photos

Loc: 334111

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 2/5/2024

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing west along the access road which is rutted and not maintained.



## Inspection Photos



**Photo 2.** Facing west along the access road which is rutted and not maintained.



Inspection Photos



**Photo 3.** Facing north at the location.



Inspection Photos



**Photo 4.** Facing northwest toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:334111 | Date: 2/5/2024

Inspection Photos



Photo 5. The operator name has peeled off the sign..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:334111 | Date: 2/5/2024