

Inspection Photos

Loc: 334204

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 2/5/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access road. This culvert near the wellsite is damaged and needs to be replaced.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:334204 | Date: 2/5/2024

Inspection Photos



Photo 2. Facing southeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:334204 | Date: 2/5/2024

Inspection Photos



Photo 3. Facing southeast at the location. Unused areas of the location are reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:334204 | Date: 2/5/2024