

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWNW

Location ID: 334807

Date: 1/31/2024



North End of Location – Photo #09033



Wellheads – Photo #09034

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWNW

Location ID: 334807

Date: 1/31/2024



Separators – Photo #09039



Tank Battery – Photo #09037

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWNW

Location ID: 334807

Date: 1/31/2024



Open-Ended Load Line – Photo #09038