

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 5824 From entrance to location




Photo # 5825 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 5826 Location



Photo # 5827 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Feb 5, 2024 at 2:19:25 PM  
CO

Photo # 5828 Location



Feb 5, 2024 at 2:21:09 PM  
CO

Photo # 5829 Stockpiled soils with no BMP's & debris