

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 1/31/2024



Jan 31, 2024 at 13:03:01
De Beque CO 81630
United States



Jan 31, 2024 at 13:03:35
De Beque CO 81630
United States

Location Entrance – Photo #09041

Wellheads – Photo #09043

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 1/31/2024



Separators – Photo #09048



Tank Battery – Photo #09046

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 1/31/2024



Lack of Stabilization – Photo #09044



Lack of Stabilization – Photo #09045

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 1/31/2024



Lack of Stabilization – Photo #09047



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09049**