

Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732



Photo # 5669 From entrance to location



Photo # 5670 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732



Photo # 5671 Location



Photo # 5672 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732



Photo # 5673 Location



Photo # 5674 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732



Photo # 5675 Location



Photo # 5676 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC PD21 Pad
Location #: 334732



Photo # 5677 Unused equipment



Photo # 5778 Tank battery containment starting to buckle & has separated from one of the support braces.