

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2024

Submitted Date:

02/06/2024

Document Number:

710500162**FIELD INSPECTION FORM**Loc ID 321180 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 558 CASTLE PINES PKWY UNIT B-4City: CASTLE PINES State: CO Zip: 80108**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Highberger, Kathryn		kathrynhighberger@gmail.com	
Freese, Steve		steve.freese@state.co.us	Land Board
Bongers, Brent		bbongers@impetroresources.com	
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276262	WELL	PA	07/17/2017	OW	009-06628	STATE OF COLORADO 3-16	EI
321180	LOCATION	CL			-	STATE OF COLORADO-635S46W 16NENE	EI

General Comment:

This is an Environmental Inspection for the State of Colorado 3-16 API# 05-009-06628 Plugged and Abandon well location located in Baca County Colorado.

Inspected Facilities									
Facility ID:	276262	Type:	WELL	API Number:	009-06628	Status:	PA	Insp. Status:	EI
Facility ID:	321180	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: OTHER E&P WASTE

Estimated Spill Volume: _____

Comment: The north side of the location appears to have impacted soils with signs of erosion. See attached Photo Log

Corrective Action: The operator shall file a Form 19 and investigate the potential historical release in accordance with Rule 912.b.(1)E

Date: 02/07/2024

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
All previously assigned CAs assigned to the location still apply	sanchezcc	02/06/2024
The north side of the location appears to have impacted soils with signs of erosion. The operator shall file a Form 19 and investigate the potential historical release in accordance with Rule 912.b.(1)E	sanchezcc	02/06/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500165	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6420771