

Operator: EXTRACTION OIL & GAS INC
Location Name: BOX ELDER H-61S65W 31NENE
Loc ID: 319761
Inspection: 709400738



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c. The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date the location was observed out of compliance.

CA Resolution: Operator has addressed and cleared weeds identified, as well as trash found on location to comply with Rule 606.c.