

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5491 From entrance to location



Photo # 5492 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5493 Location



Photo # 5494 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5495 Location



Photo # 5496 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5497 Location



Photo # 5498 Unlabeled chemical drum

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5499 Debris