



FORM
INSP

Rev
X/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/31/2024
Submitted Date:
01/31/2024
Document Number:
714200627

Loc ID
322600

Inspector Name:
Santistevan, Brittani

On-Site Inspection ☐
2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Status Summary:
☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED
Findings:
3 Number of Comments
1 Number of Corrective Actions
☒ Corrective Action Response Requested
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	All Inspections

General Comment:

Date Run: 2/7/2024 Doc [#714200627]

Page 1 of 3

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	unused/disconnected gas meter on previous tank battery location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	02/07/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground.</p> <p>On Wednesday, January 31, 2024 at approximately 10:40, I, Inspector Brittani Santistevan, conducted an on-site inspection at EASTON 2, G12-19 (Noble Energy, Inc.), at location ID: 322600 in WELD COUNTY, Colorado.</p> <p>While there, I observed a plugged and abandoned location.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. It appears the wellheads associated with this equipment has been plugged and abandoned, unused/disconnected gas meter remains on tank battery location. Remove to comply with Rule 606. (Corrective Action Date: February 7, 2024) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	01/31/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403672527	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6413859
714200628	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6413843