

Interim and Stormwater Inspection

January 10, 2024

Operator: KP Kauffman Company- #46290

Location ID: 317803

Inspection Document #: 709400744

Weld County, CO

SWNW Section 35 T2N R67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Peter Montoya B-1
Facility ID: 317803



Photo 1. Photo taken of location sign, facing north.



Photo 2. Photo taken of pump jack. Photo taken facing northwest.



Inspection Photos
Location Name: Peter Montoya B-1
Facility ID: 317803



Photo 3. Photo taken of tank battery. Photo taken facing northwest.



Photo 4. Photo taken of unmanaged weeds (kochia & russian thistle) along perimeter fence. Photo taken facing north.



Inspection Photos
Location Name: Peter Montoya B-1
Facility ID: 317803



Photo 5. Photo taken of unmanaged weeds (kochia & russian thistle) along backside of separator. Photo taken facing southeast.



Photo 6. Photo taken of unmanaged weeds (kochia & russian thistle) along access road and around electrical boxes. Photo taken facing southeast.

