

Interim and Stormwater Inspection

January 11, 2024

Operator: Extraction Oil & Gas- #10459

Location ID: 320433

Inspection Document #: 709400746

Adams County, CO

NWSE Section 3 T2S R66W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name:HRS-TR Ranch 10-3
Facility ID: 320433



Photo 1. Photo taken of location sign, facing north.



Photo 2. Photo taken of well head. Photo taken facing northwest.

Inspection Photos
Location Name:HRS-TR Ranch 10-3
Facility ID: 320433



Photo 3. Photo taken of tank battery. Photo taken facing east.



Photo 4.Photo taken of weeds (kochia & russian thistle) and stabilizing tackifier . Photo taken facing south.

Inspection Photos
Location Name:HRS-TR Ranch 10-3
Facility ID: 320433



Photo 5. Photo taken of unmanaged weeds (kochia & russian thistle) on site. Photo taken facing southwest.



Photo 6. Photo taken of reseeded area along access road and wattles. Photo taken facing southeast.