

Interim and Stormwater Inspection

January 11, 2024

Operator: KP Kauffman Company- #46290

Location ID: 320455

Inspection Document #: 709400748

Adams County, CO

NWSW Section 28 T1S R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BoxElder 13-28
Facility ID: 320455



Photo 1. Photo taken of location sign, facing south.



Photo 2. Photo taken of well head. Photo taken facing northwest.



Inspection Photos
Location Name: BoxElder 13-28
Facility ID: 320455



Photo 3. Photo taken of tank battery. Photo taken facing southeast.



Photo 4. Photo taken of mowed vegetation on site and up to adjacent field. Photo taken facing west.

Inspection Photos
Location Name: BoxElder 13-28
Facility ID: 320455



Photo 5. Photo taken of adjacent field and crop over. Photo taken facing southeast.



Photo 6. Photo taken of tank battery/buried tank and mowed vegetation. Photo taken facing northwest.