

Interim and Stormwater Inspection

January 11, 2024

Operator: KP Kauffman Company- #46290

Location ID: 320282

Inspection Document #: 7094007

Adams County, CO

SESE Section 28 T1S R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BoxElder 28-1
Facility ID: 320282



Photo 1. Photo taken of location sign, facing east.



Photo 2. Photo taken of well head. Photo taken facing northwest.



Inspection Photos
Location Name: BoxElder 28-1
Facility ID: 320282



Photo 3. Photo taken of dumped trash on well pad. Photo taken facing northwest.



Photo 4. Photo taken of well pad access road and weeds (kochia & russian thistle). Photo taken facing south.

Inspection Photos
Location Name: BoxElder 28-1
Facility ID: 320282



Photo 5. Photo taken of trash on site. Photo taken facing southeast.



Photo 6. Photo taken of tank battery/buried tank and mowed vegetation. Photo taken facing southeast.

Inspection Photos
Location Name: BoxElder 28-1
Facility ID: 320282



Photo 5. Photo taken of adjacent field and crop over and debris dumped on site. Photo taken facing southeast.



Photo 6. Photo taken of adjacent field and crop over. Photo taken facing southeast.