

# Interim and Stormwater Inspection

January 30, 2023

Operator: Kerr McGee Oil & Gas- #47120

Location ID: 322551

Inspection Document #: 709400756

Weld County, CO

NWSW Section 29 T2N R65W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: UPRR 38 PAN AM T-True 1

Location ID: 322551



Photo 1. Photo taken of location sign, facing west.



Photo 2. Photo taken of well heads. Photo taken facing northeast.

Inspection Photos

Location Name: UPRR 38 PAN AM T-True 1

Location ID: 322551



**Photo 3.** Photo taken of tank battery on pad. Photo taken facing west.

**Photo 4.** Photo taken of reeling west side of tank battery pad. Photo taken facing west.



Inspection Photos

Location Name: UPRR 38 PAN AM T-True 1

Location ID: 322551



**Photo 5.** Photo taken of topsoil stockpile covered in weed (Kochia & russian thistle) . Photo taken facing north.



**Photo 6.** Photo taken of adjacent undisturbed vegetation to site for reference. Photo taken facing northeast.



Inspection Photos  
Location Name: UPRR 38 PAN AM T-True 1  
Location ID: 322551



**Photo 7.** Photo taken of weeds (kochia) on well pad. Photo taken facing northwest.



**Photo 8.** Photo of well pad depicting unmanaged weeds on the left side of photo (see arrow) . Photo taken facing south.