

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2024

Submitted Date:

02/07/2024

Document Number:

690012260

## FIELD INSPECTION FORM

 Loc ID 484314 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                   | Comment                         |
|--------------|-------|-------------------------|---------------------------------|
| , Oxy        |       | ECMCInspections@Oxy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type         | Status | Status Date | Well Class | API Num | Facility Name                       | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|-------------------------------------|-------------|
| 484315      | TANK BATTERY | AC     | 04/18/2023  |            | -       | Herrick 21-3N-66W NENW Tank Battery | AO          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |  |       |
|--------------------|----------------------|--|-------|
| Type               | BATTERY              |  |       |
| Comment:           |                      |  |       |
| Corrective Action: |                      |  | Date: |
| Type               | TANK LABELS/PLACARDS |  |       |
| Comment:           |                      |  |       |
| Corrective Action: |                      |  | Date: |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |              |  |       |
|--------------------|--------------|--|-------|
| Type               | TANK BATTERY |  |       |
| Comment:           |              |  |       |
| Corrective Action: |              |  | Date: |
| Type               | SEPARATOR    |  |       |
| Comment:           |              |  |       |
| Corrective Action: |              |  | Date: |

**Equipment:**

| Type                              |     |  | corrective date |
|-----------------------------------|-----|--|-----------------|
| Type: Gas Meter Run               | # 0 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |
| Type: Horizontal Heated Separator | # 1 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |
| Type: Emission Control Device     | # 0 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |
| Type: Bird Protectors             | # 1 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |

| <b>Tanks and Berms:</b> |   |          |           |         |                       |       |
|-------------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents                | # | Capacity | Type      | Tank ID | SE GPS                |       |
| CRUDE OIL               | 1 | 300 BBLs | STEEL AST |         | 40.217330,-104.784360 |       |
| Comment:                |   |          |           |         |                       |       |
| Corrective Action:      |   |          |           |         |                       | Date: |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type | Tank ID | SE GPS |       |
|--------------------|---|----------|------|---------|--------|-------|
| PRODUCED WATER     | 1 | OTHER    |      |         | ,      |       |
| Comment:           |   |          |      |         |        |       |
| Corrective Action: |   |          |      |         |        | Date: |

**Paint**

|                  |        |
|------------------|--------|
| Condition        |        |
| Other (Content)  |        |
| Other (Capacity) | 48 Bbl |
| Other (Type)     |        |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 484315 Type: TANK API Number: - Status: AC Insp. Status: AO

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| All wells serviced by this battery have been disconnected from thier respective flow lines. | carlilec | 02/07/2024 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 690012261    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6421521">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6421521</a> |