



WELL SITE INSPECTION FORM

WELL NAME Tuttle #2 API NUMBER 05 - 121 - Unpermitted
OPERATOR J.C. Westmoreland PERMIT NUMBER None
LOCATION NE SW 28 - 2N - 54W COUNTY WASHINGTON
FIELD Ruby INSPECTOR Binkley

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) _____ FAIL(N) _____ DATE _____ FN _____ FD _____ WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING 10-25-89

CASING SIZE 8 5/8 DEPTH SET 200t CMT VOL _____ WOC _____

CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____

RIG KOPCO #3 BOP'S _____ CONTACT Westmoreland thru Snowden
867-6275

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____

MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____

BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS MaryAnn Snowden - 867-6275

J.C. Westmoreland - Contract prumper

West is planning to get bond and permit - ASAP
to re-enter the Kingwood - Tuttle #2 well.
I caught him on site today after six months of attempting
to find the person responsible for this operation.