



WELL SITE INSPECTION FORM

WELL NAME Tuttle 2
OPERATOR Westmoreland
LOCATION NESW 28-2N-54W
FIELD Ruby

API NUMBER 05 - 121 - 6895
PERMIT NUMBER 891181
COUNTY Washington
INSPECTOR Binkley

AL/PA/DA INSPECTION RESULTS:

PASS(Y) _____ FAIL(N) _____ DATE _____

WELL STATUS:

FN _____ FD X WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING 1-24-90

CASING SIZE 8 5/8 DEPTH SET ✓ CMT VOL Reentry WOC _____

CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____

RIG _____ BOP'S _____ CONTACT J. C. Westmoreland

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION FT Morgan 9/6 Snowden 06

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____

MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____

BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS Road blowed in with stone - stuck in road.
Rig working.