



WELL SITE INSPECTION FORM  
(DRILLING AND PLUGGING)



Well Name Tuttle 2 API Number 05 - 121 - 6895  
Operator Westmoreland Permit # 891181  
Location NE SW 28-2N-54 County Wash -  
Field Ruby Inspector Birdsey

AL/PA/DA Inspection Results:

Well Status:

Pass(Y)      Fail(N)      Date      ND      DG      WO X PR      SI      TA     

Date of Inspection Before/During Drilling                     

Surf. Csg. Size      Setting Depth      Cmt. Vol.      WOC time       
Consistent with APD casing Program? YES      NO      Returns       
Rig      BOP'S      Stage Tool Depth      Cmt. Vol.     

Date of Inspection Before/During/After Completion                     

Prod. Csg. Set?      Completion Rig/Activity                       
Drilling Pits: Closed      Open      Wellhead Installed:      Sign: Yes      No       
Tank ID: Yes      No      N/A      Skim Tank/Pit:      Prod. Tanks: ( )      BBLs  
Equipment                      Meter Run: Yes      No       
Bradenhead Press:      Fluid: No      Yes      Type      Well Cat.     

AL/PA/DA Inspection

Date Plugged:                      Date Permit Expired:                       
Hole Plugged: Yes      No      Pits Backfilled: Yes      No       
Material Buried: Yes      No      N/A      Site Clean: Yes      No       
Bond Release OK: Yes      No      Fed      Hole Marker: Yes      No     

Date of Safety/Status Inspection 7-11-91

Comments: Rig over hole. possibly TA.  
Westmoreland attempting to sell rig.  
Hit joint in lower hole after trying in  
production casing. Plans to sell drill rig  
and install w/o rig.  
Request for 5

Violations: Yes      No      Notice Sent: Yes      No      Date Sent: