

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2024

Submitted Date:

02/07/2024

Document Number:

701008126

**FIELD INSPECTION FORM**

Loc ID 321603 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10713  
Name of Operator: DARRAH OIL COMPANY LLC  
Address: 125 N MARKET STE 1425  
City: WICHITA State: KS Zip: 67202

**Findings:**

- 17 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Atterbury, Mike	(316) 219-3390	mike.atterbury@darrahoil.com	
Shalberg, Greg	719-688-3547	gregshalberg@aol.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207461	WELL	PR	10/03/1983	OW	017-06396	CHAMPLIN 205 AMOCO A 2	PR

**General Comment:**

[Routine Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Tubing stored neatly next to unit		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Location is 3/4 fenced with wire		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Ancillary equipment	# 6		corrective date
Comment:	Electric panel, cathodic rectifier on REA pole (on wellhead location), propane tank for horizontal treater, electric panel, phase convertor and cathodic rectifier on REA pole at tank battery		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		

Comment: Vertical heater treater is not in use and stored neatly on location		Date:
Corrective Action:		Date:
Type: Horizontal Heater Treater	# 1	
Comment: Treater on east side of vertical treater		
Corrective Action:		Date:
Type: FWKO	# 1	
Comment: FWKO on west side of vertical treater		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: Electric motor		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment: Lufkin 320		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		38.723500,-102.533240
Comment: Tan water tank is on east side of oil tanks					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shared berms				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		38.723500,-102.533240
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	

Other (Type) _____	
--------------------	--

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No					
Comment:					
Corrective Action:					Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				

**Inspected Facilities**

Facility ID: 207461 Type: WELL API Number: 017-06396 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central tank battery for \(Chaplin 205 Amoco A-2, A-4, A-5\) 1630' S](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT