

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: DEVORE-63N66W 34NENE

Loc ID: 336458

Inspection: 690012252



Exhibit A

CA: "Sign not legible Sign not updated to reflect current operator" Capacity and National Fire Protection Association labels on produced water tanks. See photo # 6. Install sign to comply with Rule 605.g."

CA Resolution: Operator has appropriately updated and installed signage to reflect NFPA, Contents, and Capacity. This was completed for all (4) produced water vaults to comply with Rule 605.g.