



**Inspection Photos**  
**Operator: Darrah Oil Company LLC (10713)**  
**Lease: Lowe 4**  
**Facility ID/API, 207359 / 05-017-06294**




**1. Lease sign by unit**




**2. Free Water Knock Out, HHT**

Inspection Photos  
Operator: Darrah Oil Company LLC (10713)  
Lease: Lowe 4  
Facility ID/API, 207359 / 05-017-06294




3. Tank Battery



4. Back side of battery, Inadequate berms

Inspection Photos  
Operator: Darrah Oil Company LLC (10713)  
Lease: Lowe 4  
Facility ID/API, 207359 / 05-017-06294



5. NE side of battery, Inadequate berms