

Inspection Photos


Operator: Darrah Oil Company LLC (10713)

Lease: Champlin 205 Amoco A-4

Facility ID/API, 207482 / 05-017-06417



1. Lease sign by unit




2. Pumping Unit




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Darrah Oil Company LLC (10713)
Lease: Champlin 205 Amoco A-4
Facility ID/API, 207482 / 05-017-06417



3. Tubing and rods stored neatly by unit




4. Gear box leak on unit has stained the soil

Inspection Photos
Operator: Darrah Oil Company LLC (10713)
Lease: Champlin 205 Amoco A-4
Facility ID/API, 207482 / 05-017-06417



3. Stained soil in front of unit



4. Gear box leak on unit has stained the soil