


Inspection Photos
Operator: Darrah Oil Company LLC (10713)
Lease: Lowe Arnold 4
Facility ID/API, 207534 / 05-017-06469




1. Lease sign by tanks is gone, just a frame



2. HHT, FWKO

Inspection Photos
Operator: Darrah Oil Company LLC (10713)
Lease: Lowe Arnold 4
Facility ID/API, 207534 / 05-017-06469




3. Pumping unit




4. Skid mounted scrubber (Not used)

Inspection Photos
Operator: Darrah Oil Company LLC (10713)
Lease: Lowe Arnold 4
Facility ID/API, 207534 / 05-017-06469



5. Inadequate Berms



6. Inadequate berms