

Caerus  
D31 595  
Location ID: 335674



Separators and lack of stabilization/compaction



Well heads



Caerus  
D31 595  
Location ID: 335674



Chemical tanks



All well signage is lacking information



Caerus  
D31 595  
Location ID: 335674



Debris and small wildlife could be trapped



Small wildlife could be trapped



Caerus  
D31 595  
Location ID: 335674



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus  
D31 595  
Location ID: 335674



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus  
D31 595  
Location ID: 335674



Debris



Lack of stabilization/compaction



**Caerus**  
**D31 595**  
**Location ID: 335674**



**Tracking issues**



**Lack of tracking BMP's**