

Final Reclamation Inspection

February 7th, 2024

Operator: Simcoe LLC - 10749

Location ID: 307031

Inspection Document #: 714000394

La Plata County, CO

Township: SESE 19 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Paul Martin SWD (EPA) 1
Location ID: 307031

2/7/24
+37.173149,-107.641782
340° N



2/7/24
+37.173396,-107.641949
11° N

AUTHORIZED PERSONNEL ONLY

SIMCOE LLC

Well Name: PAUL MARTIN SWD #1
API #: 05-067-09682 EPA UIC #: C021235-08403
Lease #: 19499200

Surface Location: NESE SEC 19-T34N-R07W
1489' FSL 194' FEL

Latitude: 37 10 24 North Longitude: 107 38 31 West
Deg Min Sec Deg Min Sec

Nearest Intersection: 0.4 MI N CR 514 / HWY 172
La Plata County, Colorado

BP Ph No: 970-247-6916 Emergency Phone No: 911

Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: Paul Martin SWD (EPA) 1
Location ID: 307031



Inspection Photos
Location Name: Paul Martin SWD (EPA) 1
Location ID: 307031




Photo 3. Rill erosion forming on the eastern edge of the disturbance near the access point.

Inspection Photos
Location Name: Paul Martin SWD (EPA) 1
Location ID: 307031



Photo 4. View of irrigation piping debris stored in the eastern interim reclamation area.



Inspection Photos
Location Name: Paul Martin SWD (EPA) 1
Location ID: 307031



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of dormant perennial grasses and prairie sunflower.

API #: 067-09682