

Final Reclamation Inspection

February 7th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334012

Inspection Document #: 714000396

La Plata County, CO

Township: SWNE 20 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
 Location Name: Knight D2, D3, D4
 Location ID: 334012



Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: Knight D2, D3, D4
Location ID: 334012

2/7/24
+37.176706,-107.628326
86° E



Photo 2. View of the southern interim reclamation area facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09576, 09584,
09585

Inspection Photos

Location Name: Knight D2, D3, D4

Location ID: 334012



Photo 3. View of wattles no longer functioning at the base of the western cut slope and rill erosion forming up slope of the wattles.

Inspection Photos
Location Name: Knight D2, D3, D4
Location ID: 334012



2/7/24
+37.177004, -107.628149
322° NW

Photo 4. View of stained soils at well head #3.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09576, 09584,
09585

Inspection Photos
Location Name: Knight D2, D3, D4
Location ID: 334012

2/7/24
+37.177982,-107.627861
280° W



Photo 5. View of reference area comprised of smooth brome.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09576, 09584,
09585