

Final Reclamation Inspection

February 7th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326335

Inspection Document #: 714000398

La Plata County, CO

Township: NWSE 21 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gigi Shapiro A 1
Location ID: 326335



Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: Gigi Shapiro A 1
Location ID: 326335



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern interim reclamation with exposed bare soils and dominated by musk thistle and mullein. Additional reclamation is needed in this area.

API #: 067-07858

Inspection Photos
Location Name: Gigi Shapiro A 1
Location ID: 326335



2/7/24
+37.173343,-107.609919
348° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of the western interim reclamation with exposed bare soils and dominated by musk thistle and mullein. Additional reclamation is needed in this area.

API #: 067-07858

Inspection Photos
Location Name: Gigi Shapiro A 1
Location ID: 326335



Photo 4. Impacted soils observed at the well head.



Inspection Photos
Location Name: Gigi Shapiro A 1
Location ID: 326335



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of dormant perennial grasses, active horse pasture.

API #: 067-07858