

Inspection Photos

2/5/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424

Inspection Doc: 696205602

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424



Photo 1: Working pad surface lacks stabilization; BMPs to minimize erosion, degradation and sediment transport missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424



Photo 2: Line at tank not capped/plugged.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424



Photo 3: Anchors missing required marking pursuant to Rules 1003.a and 603.j.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424



Photo 4: Anchors missing required marking pursuant to Rules 1003.a and 603.j.