

# Final Reclamation Inspection

February 7th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333471

Inspection Document #: 714000399

La Plata County, CO

Township: SWNW 20 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
 Location Name: Harry Pearson A1, A3  
 Location ID: 333471



Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos

Location Name: Harry Pearson A1, A3

Location ID: 333471



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** New fence has been constructed on the northern edge of the disturbance addressing surface owner encroachment and debris storage on active pad identified in the previous inspection.

API #: 067-06846, 09392

Inspection Photos  
Location Name: Harry Pearson A1, A3  
Location ID: 333471



**Photo 3.** View of unused oil and gas equipment observed at well head #1.



Inspection Photos  
Location Name: Harry Pearson A1, A3  
Location ID: 333471

2/7/24  
+37.178818,-107.637811  
179° S



Photo 4. View of deteriorating produced water sign on location.

