

Inspection Photos
Location Name: Lansons Farm 4
Location ID: 317899



Energy & Carbon Management Commission
40.10047, -104.97341, 4920.2ft, 43°
02/08/2024 10:52:35

Photo 1 Location.



Energy & Carbon Management Commission
40.10043, -104.97297, 4904.6ft, 295°
02/08/2024 10:53:34

Photo 2 WH sign.

Inspection Photos
Location Name: Lansons Farm 4
Location ID: 317899



Photo 3 WH.



Photo 4 Ancillary Equip.