

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NENE

Location ID: 335223

Date: 2/5/2024



Location Entrance – Photo #09145



Wellheads – Photo #09148

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NENE

Location ID: 335223

Date: 2/5/2024



Separators – Photo #09146



Tank Battery – Photo #09147

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NENE

Location ID: 335223

Date: 2/5/2024



Lack of Stabilization – Photo #09150