

# Inspection Photos

Loc: 381172

Operator: CITATION OIL & GAS CORP

Inspection Date: 2/7/2024

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast along the two track access road. Ripping of the along the two track should be performed to all revegetation to occur.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:381172 | Date: 2/7/2024



## Inspection Photos



**Photo 2.** There is an erosion channel along the road closer to the location that needs to be repaired.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:381172 | Date: 2/7/2024



## Inspection Photos



**Photo 3.** Facing northeast at the location. This area has not been reclaimed and perennial vegetation has not established. The cut slope can be seen at the red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:381172 | Date: 2/7/2024



## Inspection Photos



**Photo 4.** Facing north along the cut slope which is eroded and has not been regraded back to approximate grade..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:381172 | Date: 2/7/2024



## Inspection Photos



**Photo 5.** North side of the location facing southwest. There is some cement block debris and a bare area shown at red arrows.





## Inspection Photos



**Photo 6.** Northwest side of the location facing southeast. There is an erosion channel along this area and soils are bare of vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:381172 | Date: 2/7/2024



## Inspection Photos



**Photo 7.** Facing east at the location. The location has not been reclaimed and perennial vegetation has not established.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:381172 | Date: 2/7/2024



## Inspection Photos



**Photo 8.** Facing east at the location. The location has not been reclaimed and perennial vegetation has not established.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:381172 | Date: 2/7/2024