

Inspection Photos

Loc: 380338

Operator: CITATION OIL & GAS CORP

Inspection Date: 2/7/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the wellsite location.



Inspection Photos



Photo 2. There is a metal bar and unused riser that is unmarked and unused.



Inspection Photos



Photo 3. Facing toward the wellhead which has not produced for a very long time. Well sign has fallen over.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:380338 | Date: 2/7/2024

Inspection Photos



Photo 4. Facing southwest at the location. There are areas at the location no vegetation. It appears soils may be compacted or impacted preventing vegetation growth.



Inspection Photos



Photo 5. Northeast guyline anchor facing southwest.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:380338 | Date: 2/7/2024

Inspection Photos



Photo 6. This are approximately 80'x20' has no vegetation and appears to have impacted soils...



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:380338 | Date: 2/7/2024

Inspection Photos



Photo 7. Southeast corner of the location facing northwest..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:380338 | Date: 2/7/2024