

Interim and Stormwater Inspection

January 11, 2024

Operator: Extraction Oil & Gas- #10459

Location ID: 319725

Inspection Document #: 709400746

Adams County, CO

NESE Section 35 T1N R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Champlin 78 Amoco A1
Facility ID: 319725



Photo 1. Photo taken of location sign, facing north.



Photo 2. Photo taken of well head. Photo taken facing northwest.

Inspection Photos
Location Name: Champlin 78 Amoco A1
Facility ID: 319725



Photo 3. Photo taken of tank battery. Photo taken facing east.



Photo 4. Photo taken of adjacent lands for comparison. Photo taken facing south.

Inspection Photos
Location Name: Champlin 78 Amoco A1
Facility ID: 319725



Photo 5. Photo taken of unmanaged weeds (kochia & russian thistle) on site. Photo taken facing northeast.



Photo 6. Photo taken of unmanaged weeds (kochia & russian thistle) on site. Photo taken facing east.