

Interim and Stormwater Inspection

January 30, 2023

Operator: Kerr McGee Oil & Gas- #47120

Location ID: 331731

Inspection Document #: 709400783

Weld County, CO

NESE Section 19 T2N R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dechant 9-19A
Location ID: 331731



Photo 1. Photo taken of location sign, facing south.



Photo 2. Photo taken of wellhead. Photo taken facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400783

Inspection Photos
Location Name: Dechant 9-19A
Location ID: 331731



Photo 3. Photo taken of location sign at tank battery, facing east.



Photo 4. Photo taken of tank battery on pad. Photo taken facing southeast.



Inspection Photos
Location Name: Dechant 9-19A
Location ID: 331731



Photo 5. Photo taken of weeds (kochia & russian thistle). Photo taken facing east.



Photo 6. Photo taken of weeds (russian thistle & canada thistle) on site and stormwater erosion. Photo taken facing southeast.

Inspection Photos
Location Name: Dechant 9-19A
Location ID: 331731



Photo 7. Photo taken of weeds (kochia & russian thistle) on site. Photo taken facing north.



Photo 8. Photo taken of crop field around wellhead Photo taken facing north.