

Interim and Stormwater Inspection

January 30 , 2023

Operator: Crestone Peak Resources Operating- #10633

Location ID: 405908

Inspection Document #: 709400785

Weld County, CO

SWSW Section 17 T2N R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Melbon Ranch
Location ID: 405908



Photo 1. Photo taken of location sign, facing northeast.



Photo 2. Photo taken of wells on site. Photo taken facing north east.



Inspection Photos
Location Name: Melbon Ranch
Location ID: 405908



Photo 3. Photo taken of tank battery on pad. Photo taken facing north.



Photo 4. Photo taken of weeds (kochia & russian thistle) at entrance to site. Photo taken facing south .

Inspection Photos
Location Name: Melbon Ranch
Location ID: 405908



Photo 5. Photo taken of weeds (kochia & russian thistle) Photo taken facing east



Photo 6. Photo taken of stormwater erosion on well pad perimeter. Photo taken facing south.

Inspection Photos
Location Name: Melbon Ranch
Location ID: 405908



Photo 7. Photo taken of stormwater erosion on well pad perimeter. Photo taken facing north



Photo 8. Photo taken of stormwater erosion on well pad perimeter. Photo taken facing northeast.