

Interim and Stormwater Inspection

January 30, 2023

Operator: Kerr McGee Oil & Gas- #47120

Location ID: 442542

Inspection Document #: 709400787

Weld County, CO

NWNW Section 20 T2N R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sarchet 36G-20HZ
Location ID: 442542



Photo 1. Photo taken of location sign at wellhead, facing west.



Photo 2. Photo taken of well heads. Photo taken facing northwest.



Inspection Photos
Location Name: Sarchet 36G-20HZ
Location ID: 442542



Photo 3. Photo taken of mowed vegetation on well pad. Photo taken facing east.



Photo 4. Photo taken of surrounding area for reference. Photo taken facing southeast.

Inspection Photos
Location Name: Sarchet 36G-20HZ
Location ID: 442542



Photo 5. Photo taken of weeds (kochia) on site. Photo taken facing southeast.



Photo 6. Photo of vegetation and weeds (kochia) on well pad. Photo taken facing southwest