

Caerus
L34
Location ID: 334916



Location



Location

Caerus
L34
Location ID: 334916



Location



Location

Caerus
L34
Location ID: 334916



Location



Open cap on burner assembly

Caerus
L34
Location ID: 334916



Open piping



Valves open and gas running to burner, burner is not lit and venting gas.

Caerus
L34
Location ID: 334916



Battery signage



Valve leaking