

Caerus
P33NE
Location ID: 334857



Location



Where tank battery used to be

Caerus
P33NE
Location ID: 334857



Location



Location

Caerus
P33NE
Location ID: 334857



Stored equipment or debris



Stored equipment or debris

Caerus
P33NE
Location ID: 334857



Maybe the battery sign



Signs of lack of stabilization/compaction

Caerus
P33NE
Location ID: 334857



Debris



Fencing is not outside of excavated area

Caerus
P33NE
Location ID: 334857



Fencing is not outside of excavated area



Open hole

Caerus
P33NE
Location ID: 334857



Open hole



Open hole

Caerus
P33NE
Location ID: 334857



Open hole



Stored equipment or debris

Caerus
P33NE
Location ID: 334857



Open hole



Open hole