

Caerus  
O33NE  
Location ID: 323968



Location and lack of battery signage



Location

Caerus  
O33NE  
Location ID: 323968



Location




Tank battery stairs



Caerus  
O33NE  
Location ID: 323968



Fencing is open and in disrepair



Fencing is open and in disrepair