

Inspection Photos

Location Name: GEMINI B-65N64W/31CNW1/4

Location #: 305880



Photo #1

Gemini B 31-19 (123-23616) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 75 yds.



Photo #2

Thistle Down B 31-30D, B 31-31D,

Gemini B 31-3, B 31-19,

Gemini – UPRR B31-4, B31-5, B31-6

Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources