

WELL NAME: TELNA 24-22 TR, API #: 071-08304, INSP. # 695109111




PHOTO 1: WELL SIGN



**PHOTO 2: LOCATION**



**PHOTO 3: WELLHEAD AND EQUIPMENT**





**PHOTO 4: AREA OD IMPACTED OIL NEER WELLHEAD APPEARS TO BE LEAKING HYDRUALIC HOSES. Impacted soil identified at various locations through out location. CA DATE 3-12-2024.**





**PHOTO 5: OILY WASTE IN ENGINE SKID. COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 2-13-2024.**