

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2024

Submitted Date:

02/12/2024

Document Number:

711900266**FIELD INSPECTION FORM**Loc ID 313699 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10657Name of Operator: PCR OPERATING LLCAddress: 9211 BROADWAY ST #17493City: SAN ANTONIO State: TX Zip: 78217**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	
Wehrer, Gene		gwehrer1961@outlook.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224892	WELL	SI	10/01/2022	OW	087-05285	LAUGHLIN, R J 7	SI

General Comment:

UIC ROUTINE FIR - LAST MIT 7-10-2019 MIT DUE 2024 UIC ROUTINE PERFORMED IN LIEU OF 2024 MIT

Location

Lease Road:			
Type	Access		
comment:	TWO TRACK GRASSLAND - MAINTAIN LEASE ROAD		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	REPLACE STICKER ON SIGN		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	REPLACE STICKER ON SIGN		Date:
Corrective Action:			

Good Housekeeping:			
Type	WEEDS		
Comment:	CONTROL VEGETATION AT WELLHEAD		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: NONE

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment:	NO CHANGE		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224892

Type: WELL

API Number: 087-05285

Status: SI

Insp. Status: SI

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube: Pressure or inches of Hg 0

Previous Test Pressure

MPP

(e.g. 30 psig or -30" Hg)

Inj Zone: JSND

TC: Pressure or inches of Hg 0

Previous Test Pressure

Last MIT: 07/10/2019

Brhd: Pressure or inches of Hg 0

Previous Test Pressure

AnnMTReq:

Comment: MIT DUE 2024 ROUTINE UIC PERFORMED IN LIEU OF MIT

Corrective Action:

Date:

Method of Injection:

Test Type:

Tbg psi:

Csg psi:

BH psi:

Insp. Status:

Comment:

Corrective Action:

Date:

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: LAST MIT 7-10-2019 MIT DUE 2024

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
UIC ROUTINE 2024 UIC MIT DUE IN 2024	schureky	02/12/2024