

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad

Location #: 334660



Feb 8, 2024 at 12:59:31 PM



Feb 8, 2024 at 1:00:44 PM

Photo # 6125 From entrance to location

Photo # 6126 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad

Location #: 334660



Photo # 6127 Location



Photo # 6128 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad

Location #: 334660



Photo # 6129 Location



Photo # 6130 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad

Location #: 334660



Photo # 6131 Location



Photo # 6132 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad

Location #: 334660



Photo # 6133 Holes in liner/liner needs maintenance



Photo # 6134 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad

Location #: 334660



Photo # 6135 Holes in liner/liner needs maintenance



Photo # 6136 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad

Location #: 334660



Photo # 6137 Holes in liner/liner needs maintenance



Photo # 6138 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad

Location #: 334660



Photo # 6139 Hole in liner/liner needs maintenance



Photo # 6140 Hole in liner/liner needs maintenance